

Machine Vision Accelerator

RELEASE NOTES

May 19, 2021

Copyright © 2021 CSP Inc.

All rights reserved.

ARIA Cybersecurity Solutions, which includes ARIA SDS, Myricom network adapters, and nVoy security appliances, are designed and manufactured by the High Performance Products Division of CSP Inc.

No part of this publication may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without prior written permission from CSP Inc.

All copyright, confidential information, patents, design rights and all other intellectual property rights of whatsoever nature contained herein are and shall remain the sole and exclusive property of CSP Inc. The information furnished herein is believed to be accurate and reliable. However, no responsibility is assumed by CSP Inc. for its use, or for any infringements of patents or other rights of third parties resulting from its use.

 $ARIA^{TM}$ and $nVoy^{TM}$ are trademarks of CSP Inc. Myricom[®] is a registered trademark of CSP Inc. All other trademarks are the property of their respective owners.

PRELIMINARY NOTICE

This document is in the preliminary stage and is subject to change without notice.

Publishing Information

Revision	Date	Details
1.3.0	February 19, 2021	Preliminary release.
2.0.0	March 26, 2021	Updated for 2.0.0.
2.0.1	May19, 2021	Updated for 2.0.1.

Address

ARIA Cybersecurity Solutions Product Development C/O CSP Inc. 175 Cabot Street, Suite 210

Lowell, MA 01854 Tel: (800) 325-3110

ARIA_support@ariacybersecurity.com

https://www.ariacybersecurity.com

Myricom NETWORK ADAPTERS

Contents

Summary	1
Version 2.0.1	3
New Features	3
Bug Fixes	3
Limitations	3
Known Issues	3
Version 2.0.0	4
New Features	4
Bug Fixes	4
Limitations	4
Known Issues	4
Linux Support	5
Windows Support	5
Version 1.3.0	6
New Features	
Bug Fixes	
Limitations	
Known Issues	7
Linux Support	7
Windows Support	7
Version 1.2.7	8
New Features	
Bug Fixes	
Limitations	
	8
Version 1.2.6	9
New Features	
Bug Fixes	
Limitations	
Known Issues	10

Myricom NETWORK ADAPTERS

ii ARIA MVA Release Notes



Summary

The ARIA™ Machine Vision Accelerator (MVA) solution greatly improves the performance of machine vision applications processing data from GigE Vision devices. MVA dramatically reduces the host processor overhead while providing maximum throughput when receiving GigE Stream Protocol (GVSP) content. MVA was designed for easy integration into existing GigE Vision Software Development Kits (SDKs) and native applications.

For more information about MVA, see the *ARIA Machine Vision Accelerator User Guide*.

This document describes the new features, bug fixes, known issues, and limitations for various releases of the MVA solution.

ARIA MVA Release Notes 1

Myricom NETWORK ADAPTERS

2 ARIA MVA Release Notes

Version 2.0.1

Version 2.0.1 of the ARIA MVA release contains the bug fixes, known issues, and limitations described in this section.

New Features

- (ID #277) The -p argument was added to mva_simple_recv_pr. This argument disables the packet resend feature.
- (ID #401) A makefile script is included to allow you to build demos. This file is located in /opt/mva/share/examples (Linux) or C:\MVA_Myri-10G\share\doc\examples (Windows).
- (ID #424) A simplified .msi file, appended with _do, is available. This file installs the driver and driver libraries only.
- (ID #429) A static library for MVA was added. This allows you to compile applications creating a link to mva.dll. This applies to Windows only.

Bug Fixes

- (ID #398) Modified mva_open_stream() so that it ignores the MVA_OPEN_ZEROLOSS flag if it is passed as an argument.
- (ID #427) Resolved an issue with running the rebuild.sh script on RedHat Linux version 8.3.

Limitations

- 1. Each adapter supports up to eight GVSP streams by default.
- 2. Up to 511 buffers can be queued to an MVA per stream at one time.
- 3. 10GbE line speed has been verified with 8972 byte packets (MTU 9000). Smaller packet sizes have not been extensively tested and may result in dropped packets.
- 4. MVA_OPEN_IPV6 is not supported.

Known Issues



Version 2.0.0

Version 2.0.0 of the ARIA MVA release contains the bug fixes, known issues, and limitations described in this section.

New Features

- (ID #334) The MVA adapter can receive GVSP 1.x and 2.x messages and send them to the host.
- (ID #316) The MVA adapter supports chunk payload packet types.

Bug Fixes

- (ID #260) Added -h to the myri_info help system.
- (ID #266) Added help to the myri_license program.
- (IDs #296, 301, 303, and 309) Modified the myri_bandwidth, mva_simple_recv, mva_rwdt_recv, and mva_multi_thread programs to validate inputs.
- (ID #305) Removed mva_get_set_name from the Windows package. Use mva_adapter_ name instead.
- (ID #315) Resolved an issue where unsupported payload types would cause the adapter to hang. Now the adapter drops the packets.
- (ID #330) Resolved an issue where the API was returning incomplete data to the buffer before waiting for an incomplete-final block. This caused a mismatch between the block and the buffer.
- (ID #349) Modified the mva_poll_recv() API function such that it no longer loops under certain circumstances.

Limitations

- 1. Each adapter supports up to eight GVSP streams by default.
- 2. Up to 511 buffers can be queued to an MVA per stream at one time.
- 3. 10GbE line speed has been verified with 8972 byte packets (MTU 9000). Smaller packet sizes have not been extensively tested and may result in dropped packets.
- 4. MVA_OPEN_IPV6 is not supported.

Known Issues

5

Linux Support

- CentOS 7.9, 8.3, and Stream
- RedHat 7.9 and 8.3
- Ubuntu 16.04, 18.04, and 20.04
- Debian 10.7

Windows Support

- Windows 10
- Windows Server 2016 and 2019

ARIA MVA Release Notes



Version 1.3.0

Version 1.3.0 of the ARIA MVA release contains the bug fixes, known issues, and limitations described in this section.

New Features

- (ID #75) Support for RHEL/CentOS 7.9, 8.3, and Stream was added.
- (ID #80) The MVA solution supports Linux kernels up to version 5.10.
- (ID #82) The MVA driver can be installed using InstallAnywhere (see the Machine Vision Accelerator User Guide for details).
- (ID #94) The mva_simple_recv application accepts a range for the -D (synthetic processing delay) argument.
- (ID #103) New functions for retrieving, setting, and resetting the name of an MVA adapter were added (see the MVA API Guide for details). These functions include:
 - mva_get_name()
 - mva_reset_all_name()
 - mva_reset_name()
 - mva_set_name()
- (ID #107) The MVA adapter supports the packet resend feature. For details about the
 feature, see the ARIA Machine Vision Accelerator User Guide. As part of this feature, the
 following changes were made in the API (see the MVA API Guide for details):
 - Added mva_open_stream_pr() and mva_poll_recv_pr() functions.
 - Enhanced the mva_stats and mva_block_status objects.
 - Enhanced the stream flags MVA_OPEN_ZEROLOSS, MVA_OPEN_DROP_ INCOMPLETE, and MVA_OPEN_RETURN_INCOMPLETE.
 - Added the mva_packet_resend_config object.
 - Added the MVA_BOOO_XXX flags.
- (ID #107) New example applications (mva_simple_recv_pr and mva_rwdt_recv_pr) for the
 packet resend feature were added (see the ARIA Machine Vision Accelerator User Guide for
 details).
- (ID #117) Raw, file, and extended chunk payload files are now supported.
- (ID #206) Support for Ubuntu LTS versions up to 20.04 and Debian 10.7 was added.
- (ID # 269) The API provides the mva_clear_stats() function for resetting statistics.

Bug Fixes

- (ID #55) Resolved an issue where some test examples resulted in a seg fault.
- (ID #132) Set the number of default buffers to 63 for mva_simple_recv.

- (ID #133) Resolved an issue where a seg fault would occur if the buffer size was too large.
- (ID #243) Fixed the verify block order (-V) functionality for the mva_simple_recv, mva_rwdt_recv_pr, and mva_simple_recv_pr scripts.

Limitations

- 1. Each adapter supports up to eight GVSP streams by default.
- 2. Up to 511 buffers can be queued to an MVA per stream at one time.
- 3. 10GbE line speed has been verified with 8972 byte packets (MTU 9000). Smaller packet sizes have not been extensively tested and may result in dropped packets.
- 4. MVA_OPEN_IPV6 is not supported.

Known Issues

None.

Linux Support

- CentOS 7.9, 8.3, and Stream
- RedHat 7.9 and 8.3
- Ubuntu 16.04, 18.04, and 20.04
- Debian 10.7

Windows Support

- Windows 10
- Windows Server 2016 and 2019



Version 1.2.7

Version 1.2.7 of the ARIA MVA release contains the bug fixes, known issues, and limitations described in this section.

New Features

(ID #47) The MVA solution supports Linux kernels up to version 5.5.

Bug Fixes

(ID #45) Resolved an issue where the driver would crash or lock on Ubuntu 18.04.

Limitations

- 1. Each adapter supports up to eight GVSP streams by default.
- 2. Up to 511 buffers can be queued to an MVA per stream at one time.
- 3. 10GbE line speed has been verified with 8972 byte packets (MTU 9000). Smaller packet sizes have not been extensively tested and may result in dropped packets.
- 4. MVA_OPEN_IPV6 is not supported.
- 5. MVA_OPEN_ZEROLOSS is not supported

Known Issues

Version 1.2.6

Version 1.2.6 of the ARIA MVA release contains the bug fixes, known issues, and limitations described in this section.

New Features

- 1. (ID #36) Added support for variable-sized buffers. By default, the buffer size is 508 MB, but it can be decreased down to 60 MB.
- 2. (ID #37) Added a parameter named *myri_mva_desc_count* that allows you to adjust the number of descriptors for larger buffers.

```
matrix of allowed myri_mva_desc_count
descriptors
           size
                     max buffer
   512
                          60 MB
              256
   256
             512
                         124 MB
   128
             1024
                        252 MB
   64
             2048
                         508 MB
                                  (default)
```

To set the number of descriptors in Linux:

a. Modify and uncomment the module parameter for *myri_mva_desc_count* in the script /opt/mva/sbin/myri_start_stop.

```
#add/modify/uncomment MYRI_MODULES_PARAMS lines to change defaults
#MYRI_MODULE_PARAMS=" myri_mva_desc_count=256 $MYRI_MODULE_PARAMS"
```

b. Restart the driver.

```
sudo /opt/mva/sbin/myri_start_stop restart
```

To set the number of descriptors in Window:

Set the registry key.

```
PS C:\MVA_Myri-10G> REG ADD HKLM\SYSTEM\CurrentControlSet\services\mva /v myri_mva_desc_count /t REG_DWORD /d 256
```

- b. Select Control Panel > Network and Internet > Network Connections.
- c. Disable the first and second Myri-10G PCIe NICs with MVA.
- d. Enable the first and second Myri-10G PCIe NICs with MVA. This restarts the devices.
- 3. (ID #38) Added support for CentOS 8.2 and Linux kernels up to 5.5.

Bug Fixes

None.

Limitations

- 1. Each adapter supports up to eight GVSP streams by default.
- 2. Up to 511 buffers can be queued to an MVA per stream at one time.



- 3. 10GbE line speed has been verified with 8972 byte packets (MTU 9000). Smaller packet sizes have not been extensively tested and may result in dropped packets.
- 4. MVA_OPEN_IPV6 is not supported.
- 5. MVA_OPEN_ZEROLOSS is not supported

Known Issues